



REPRESENTATIVE SAMPLE CERTIFICATION

The individual who collected the sample should complete this certification in its entirety. A complete lab report, QA/QC, and chain-of-custody should be submitted.

Generator Name:	The Boeing Company		
Generator:	PO Box 3707		
Address:	Seattle, WA 98124		
Site Address: (If Different)	8811 East Marginal Way South Tukwila, WA 98108		
Sampler's Name:	David Nelson / Brett Borgeson		
Phone Number:	425-778-0907		
Name Of Waste:	stabilized soil / untreated soil		
Date Sampled:	8/20/08 and 1/14/08	Sample Type (circle):	COMPOSITE <u>GRAB</u>
Type of Waste (circle):	<u>SOLID</u>	SEMI-SOLID	SLUDGE LIQUID OTHER
Name of Laboratory:	Analytical Resources, Inc.		
Applicable Sample #'s:	MF11A - MF11J and NL33A - NL33 T		
COMMENTS (if any):	Laboratory analytical reports have been provided under separate cover.		
I hereby certify to the best of my knowledge and belief the sample described above is representative of the waste to be handled and has been collected in accordance with U.S. EPA §40 CFR 261.20(e) guidelines or equivalent rules. The information/lab report submitted for review is complete and accurate.			
<u>Kathryn F. Hartley</u>		<u>9/19/08</u>	
AUTHORIZED REPRESENTATIVE SIGNATURE		DATE	
<u>Kathryn F. Hartley</u>		<u>Sr. Staff Scientist</u>	
AUTHORIZED REPRESENTATIVE (PRINTED NAME)		TITLE	
<u>Landau Associates</u>			
COMPANY			